UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,370,414 B2 Page 1 of 1

APPLICATION NO.: 10/810041
DATED: May 13, 2008
INVENTOR(S): Donald A. Ice

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4

Line 13, change "lead frame connector 14" to --lead frame connector 12--

Line 20, change "with four" to --with five--

Line 21, change "and five" to -- and four--

Column 5

Line 4, change "casing 32 is" to --casing is--

Line 7, change "injection molding process" to --injection molding process 66--

Line 57, change "connector 12 to the PCB 50" to --connector 12 or 22 to the PCB 50--

Signed and Sealed this

Thirtieth Day of March, 2010

David J. Kappos Director of the United States Patent and Trademark Office